

97	Three phase power factor meter	1
	i. 10Amp/20 Amp, 250V/500V	
98	Single phase power factor meter	1 no each
	i. 5 Amp/10 Amp, 110V/250V	
	ii. 10 Amp/20 Amp, 250V/500V	
99	Ammeter	1 no each
	i. Moving Iron Type - 5 Amp, 10 Amp, 20 Amp	
	ii. Moving Coil Type - 1 Amp, 5 Amp, 10 Amp, 20 Amp	
100	Voltmeter	1 no each
	i. Moving Iron Type - 110V, 250V, 500V	
101	Stroboscope	1
102	CT- 100/5Amp, 100/1 Amp .	1 no each
	50 Amp/5Amp, 50 Amp/1 Amp	
	PT - 500V/250V, 500/110V	
103	Clamp meter - 50 Amp, 100 Amp, 400 Amp	1
104	Multimeter for measurement of V_{ac} , V_{dc} , I_{ac} , I_{dc} , Resistance & Continuity	1
105	20 MHz Dual Trace CRO.	1
106	100 MHz Dual channels Digital storage oscilloscope.	1
107	Contact type & Non Contact type tachometer for the measurement of speed.	1
108	Transformer oil testing setup.	1
109	Dual Reguated Variable dc power supply 0-30V, 2Amp.	1

4 pm
Principal 20.4.18
R. T. J., Anandpur